



V8 XJ Series/XK

DATE 08/03

307-14

SERVICE

TECHNICAL BULLETIN

Shift Quality Issues/Harsh Engagement With
Engine Cold – ZF 5HP26 –
Install New Transmission Control Module

MODEL
2000-02 MY XK Range
2000-03 MY V8 XJ Series
VIN
A00083-A30644
F00103-F59525

Issue:

On some 2000-02 MY XK NA vehicles and 2000-03 MY XJ vehicles within the above VIN ranges, customers complain of the following transmission shift quality issues, most noticeable when the engine air intake temperature is between 20°C and 30°C and when the engine coolant temperature is below 40°C. Under these conditions the engine speed will increase to 1300 rpm for an initial 30 seconds and then reduce to 1000 rpm. During the initial period when the engine speed is at 1300 rpm, the customer may complain of the following conditions:

- With no throttle application the transmission hesitates and then thumps into gear when shifting from neutral to drive.
- With no throttle application the transmission hesitates and then thumps into gear when shifting from neutral to reverse.

Action:

In case of a confirmed customer complaint of the above condition on vehicles within the above VIN ranges, install a new Transmission Control Module (TCM) as described below.

Note: If any DTCs are stored in the TCM or Engine Control Module (ECM), carry out any repairs as a separate Warranty Claim and before installing the new TCM.

WORKSHOP PROCEDURE

1. Install new TCM (see Workshop Manual, JTIS CD ROM, section: 307-01A, SRO 44.15.32).

Parts Information:

DESCRIPTION

Revised TCM

PART NUMBER

LJD 2401AC

QTY

1

Warranty Information:

Warranty claims should be submitted quoting the information found in the table below. This will result in payment of the stated time and, where applicable parts/miscellaneous expense codes as listed.

Description	SRO	Time	Causal Part Number
Install new TCM - XJ N/A	44.15.32	0.3 hrs.	LJE 2401AB
Install new TCM - XK N/A	44.15.32	0.2 hrs.	LJE 2401AB