

XJ Range

DATE **25 Sep 2006** 

NUMBER XJ211-003

**SERVICE** 

### **TECHNICAL BULLETIN**

SECTION: 211-04 – STEERING COLUMN

**Steering Wheel Alignment** 

**AFFECTED VEHICLE RANGE:** 

XJ Range VIN G49701 onwards

Model Year: 2006 onwards

### **CONDITION SUMMARY:**

#### STEERING WHEEL ALIGNMENT DIAGNOSIS

**Situation:** This bulletin is to provide diagnostic clarification for steering wheel alignment. Steering wheel alignment may be required during the initial vehicle preparation inspection road test or following a customer complaint about a vehicle that has only recently entered service and does not show evidence of any impact damage.

**Action:** If the steering wheel appears misaligned and there is no evidence of impact damage, refer to the Repair Procedure detailed in this bulletin to evaluate steering wheel misalignment and prevent unnecessary adjustments to the steering wheel.

### **PARTS:**

No parts required. Diagnostic information purposes only.

### **WARRANTY**:

NOTE: Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to DDW to obtain the latest repair time.

DDW requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.

Description	SRO	Time (Hours)	Condition Code	Causal Part
Align steering wheel	57.60.02	8.0		C2C 20159

Normal warranty policy and procedures apply.

NOTE: The information in Technical Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers." If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Jaguar service facility to determine whether the bulletin applies to a specific vehicle.

© Jaguar 2006 Page 1 9/22/2006




# **TECHNICAL BULLETIN**

NUMBER XJ211-003

### REPAIR PROCEDURE

#### **EVALUATE STEERING WHEEL ALIGNMENT**

- 1. Raise the vehicle on a suitable lift.
- 2. Remove the vehicle undertray
- 3. With assistance, rotate the steering wheel to align the steering column to the boss on the steering rack pinion housing. (Figure 1)



- 4. Lower the vehicle.
- 5. Visually check the alignment of the steering wheel.
- 6. If the steering wheel alignment is less than ±3°, no further action is required.

### **ALIGN STEERING WHEEL**



WARNING: The safety precautions detailed in the Workshop Manual relating to Supplementary Restraint Systems (SRS) must be adhered to.

NOTE: Global Technical Reference (GTR) lookup sequence is as follows: GTR Home > NAS > Service Information/ X350 - XJ/2006 > Workshop Manuals > Bookmark "Body and Paint/501-20B: Supplemental Restraint System/Removal and Installation" Link "Driver Air Bag Module (76.73.39)"

- 1. If the steering wheel alignment is greater than ±3°, photograph the misalignment.
- 2. Refer to GTR section 501-20B: Supplemental Restraint System operation 76.73.39 and remove the Driver Air Bag Module from the steering wheel.



## TECHNICAL BULLETIN

NUMBER XJ211-003

 $\triangle$ 

NOTE: Global Technical Reference (GTR) lookup sequence is as follows:
GTR Home > NAS > Service Information/ X350 – XJ/2006 > Workshop Manuals > Bookmark
"Chassis/Steering System/211-04: Steering Column/Removal and Installation" Link "Steering
Wheel (57.60.01)"

- 3. Refer to GTR section 211-04: Steering Column operation 57.60.01 and remove the steering wheel.
- 4. Adjust the steering wheel to correct alignment.
- 5. Refer to GTR section 211-04: Steering Column operation 57.60.01 and install the steering wheel.
- 6. Refer to GTR section 501-20B: Supplemental Restraint System operation 76.73.39 and install the Driver Air Bag Module from the steering wheel.
- 7. Raise the vehicle on a suitable lift.
- 8. Install the vehicle undertray.
- 9. Road test the vehicle to confirm the steering wheel alignment is within the ±3° tolerance, when driving straight ahead on a level surface, and that the vehicle steering alignment is correct.

 $\triangle$ 

NOTE: Any other steering alignment repairs are to be carried out as a separate Warranty Claim. Vehicle geometry machine print outs from before and after any steering alignment adjustments are to be submitted with warranty claim.

- 10. If the steering wheel is straight and level, and the vehicle does not track correctly during the road test, perform the following:
  - Reset the front individual toe to specification relative to the rear axle thrust line while maintaining the straight steering wheel position (i.e. Four-wheel alignment).
  - Road test the vehicle to confirm the steering wheel alignment is within the ±3° tolerance when driving straight ahead on a level surface, and that the vehicle alignment is correct.
- 11. Raise an Electronic Product Quality Report (EPQR) with the following information:
  - Photographic evidence of the alignment error, where possible.
  - Details as to the extent of steering wheel misalignment that was corrected.
  - An indication of the degree of initial steering wheel misalignment by stating the degree that corresponds most accurately to the misalignments (6°, 12°, 18° or 24°) illustrated in Figure 2.

