

# TECHNICAL BULLETIN

 <b>JAGUAR</b> SERVICE	<b>MIL Illumination – DTC P0441 – Service Action S672</b>	<b>18-51</b>
	MODEL XJS (4.0L) 1996 MY VIN 225350 - 226645	DATE 7/96

Remove and destroy Bulletin 18-51, Amended 9/96.  
Replace with this Bulletin.  
Revised text is marked with a bar and in **bold text**.

## ISSUE:

Some 1996 MY XJS vehicles within the above VIN ranges may experience illumination of the Malfunction Indicator Lamp (MIL) caused by DTC P0441 being falsely registered in the Engine Control Module (ECM).

This condition can be rectified by replacing both of the Programmable Read Only Memories (PROMs) with new PROMs from the appropriate modification kit.

## ACTION:

Refer to Technical Bulletin 18-52, dated 4/97. The software revisions for Service Action S672 to solve the above complaint were incorporated in the PROMs designed for Service Action S676.