

View

Models: X-Type

X-Type Estate

Title: FAQ 23501 - X-Type Headlight Connectors

Engineer Waller, Keith (K.)

Name:

Last 07-JUN-05

Modified:

Category: Electrical

Symptom: 201000 Lighting Systems

Content: If any instances are encountered where the connector to the head light bulbs have overheated, please repair the connector, do not replace the light assembly, Part numbers 418-411-76 and 418-411-77 have now been placed in the harness repair kit to aid this process, 418-411-76 has a clear insulator and should be used on the earth terminal on the rear of the light bowl and 418-411-77 has a brown insulator and should be connected to the rear of the bulb. .Please view the attached files.

Files: [DSCN1379.JPG](#)

[DSCN1234.JPG](#)

Print 

Has this answered your question? Yes No

(c) Jaguar 2001/5 (Rel. 1.064)