



S-TYPE

DATE 01/05

S307-18

SERVICE

TECHNICAL BULLETIN

Automatic Transmission Remove/Install –
New Workshop Procedure –
Revised Labor Times

MODEL 2003 MY-ON
S-TYPE
VIN M44998-ON

Issue:

The replacement procedure for automatic transmissions and associated labor times have been revised on GTR.

The current workshop procedure calls for driveshaft removal. This is not required since the driveshaft can be detached from the transmission and tied aside.

In addition, the engine no longer needs to be supported using the engine support beam. In the new workshop method the engine is braced from underneath using the rubber blocks supplied with the Nike Powertrain Assembly Jack (Special Service Tool HJT1200-2).

Action:

To remove/install an automatic transmission, refer to the new workshop method in Section 307-01, SRO 44.20.01 on GTR.

Global Technical Reference (GTR) Workshop Manual Information:

Dealer access: https://hub.franchise.jaguar.com

Internet access: http://www.jaguartechno.com

Parts Information:

Table with 3 columns: DESCRIPTION, PART NUMBER, QTY. Row 1: N/A, -, -

Warranty Information:

Table with 4 columns: Description, SRO, Time, Causal Part Number. Row 1: Automatic Transmission Assembly - Replace 3.0L, 44.20.01, 4.0 hrs., -

NOTE: THE INFORMATION IN TECHNICAL BULLETINS IS INTENDED FOR USE BY TRAINED, PROFESSIONAL TECHNICIANS WITH THE KNOWLEDGE, TOOLS, AND EQUIPMENT TO DO THE JOB PROPERLY AND SAFELY. IT INFORMS THESE TECHNICIANS OF CONDITIONS THAT MAY OCCUR ON SOME VEHICLES, OR PROVIDES INFORMATION THAT COULD ASSIST IN PROPER VEHICLE SERVICE. THE PROCEDURES SHOULD NOT BE PERFORMED BY "DO-IT-YOURSELFERS." DO NOT ASSUME THAT A CONDITION DESCRIBED AFFECTS YOUR CAR. CONTACT A JAGUAR DEALER TO DETERMINE WHETHER THE BULLETIN APPLIES TO YOUR VEHICLE.

