

XK

DATE 05/04

100-23

SERVICE

TECHNICAL BULLETIN

Drive Belt Noise After Cold Start – Supercharger – Revised Drive Belt Available

MODEL 2003-04 MY XKR VIN A30645-A41576

Issue:

On some 2003-04 MY XKR vehicles, customers may have a concern with noise from the supercharger drive belt after a cold start.

A revised drive belt has been released to address this concern.

Action:

Should a customer express concern of a noise from the supercharger drive belt from cold start, remove the supercharger drive belt to confirm that the noise stops. If so, install a new modified supercharger drive belt, referring to Workshop Manual, section: 303-05, SRO 18.50.08).

Global Technical Reference (GTR):

Dealer Access: https://hub.franchise.jaguar.com
Internet access: https://www.jaguartechinfo.com

Parts Information:

DESCRIPTIONPART NUMBERQTYSupercharger drive beltC2C 262351

Warranty Information:

Warranty claims should be submitted quoting the information found in the table below. This will result in payment of the stated time and, where applicable parts/miscellaneous expense codes as listed.

| Description | SRO | Time | Causal Part Number |
|---------------------------------------|----------|----------|-----------------------|
| Install a new supercharger drive belt | 18.50.08 | 0.6 hrs. | C2C 26235 |

NOTE: THE INFORMATION IN TECHNICAL BULLETINS IS INTENDED FOR USE BY TRAINED, PROFESSIONAL TECHNICIANS WITH THE KNOWLEDGE, TOOLS, AND EQUIPMENT TO DO THE JOB PROPERLY AND SAFELY. IT INFORMS THESE TECHNICIANS OF CONDITIONS THAT MAY OCCUR ON SOME VEHICLES, OR PROVIDES INFORMATION THAT COULD ASSIST IN PROPER VEHICLE SERVICE. THE PROCEDURES SHOULD NOT BE PERFORMED BY "DO-IT-YOURSELFERS." DO NOT ASSUME THAT A CONDITION DESCRIBED AFFECTS YOUR CAR. CONTACT A JAGUAR RETAILER TO DETERMINE WHETHER THE BULLETIN APPLIES TO YOUR VEHICLE.

