



X-TYPE

DATE 08/05

XT206-08

SERVICE

TECHNICAL BULLETIN

Parking Brake Cable Adjustment – Revised Specification

MODEL 2002 MY-ON X-TYPE
VIN C00001-ON

Issue:

The parking brake cable adjustment specification has changed. The gap between the parking brake caliper lever and the stop which was 0.1 mm to a maximum of 1 mm, has changed to 0.1 mm to a maximum of 1.5 mm.

Action:

To carry out the new parking brake cable adjustment measurement, see Global Technical Reference GTR Workshop Manual, section: 206-05, SRO 70.35.10.

Note: On early X-TYPE vehicles converted to manual adjusters under Recall R957, refer procedure for 2003 MY or later vehicles.

Global Technical Reference (GTR) Workshop Manual Information:

Dealer access: https://hub.franchise.jaguar.com
Internet access: http://www.jaguartechno.com

Parts Information:

Table with 3 columns: DESCRIPTION, PART NUMBER, QTY. Row 1: N/A, -, -

Warranty Information:

Table with 4 columns: Description, SRO, Time, Causal Part Number. Row 1: N/A, -, -, -

NOTE: THE INFORMATION IN TECHNICAL BULLETINS IS INTENDED FOR USE BY TRAINED, PROFESSIONAL TECHNICIANS WITH THE KNOWLEDGE, TOOLS, AND EQUIPMENT TO DO THE JOB PROPERLY AND SAFELY. IT INFORMS THESE TECHNICIANS OF CONDITIONS THAT MAY OCCUR ON SOME VEHICLES, OR PROVIDES INFORMATION THAT COULD ASSIST IN PROPER VEHICLE SERVICE. THE PROCEDURES SHOULD NOT BE PERFORMED BY "DO-IT-YOURSELFERS." DO NOT ASSUME THAT A CONDITION DESCRIBED AFFECTS YOUR CAR. CONTACT A JAGUAR DEALER TO DETERMINE WHETHER THE BULLETIN APPLIES TO YOUR VEHICLE.

