

TECHNICAL BULLETIN



Pirelli P5 Discontinued – Replace with P4000 Super Touring

04-21

MODEL All 1984-92 MY

DATE 4/96

ISSUE:

The Pirelli P5 tire is being discontinued. As a replacement Pirelli is now offering the P4000 Super Touring with a V speed rating in the 15" sizes Jaguar has previously used. The replacement tire has been approved by Jaguar Cars.

The model applications affected are:

1988-92	Sedan Range	equipped with P5 in size 205/70 VR 15.
1984-88	XJS	equipped with P5 in size 215/70 VR 15.
1984-86	Series III	equipped with P5 in size 215/70 VR 15.

ACTION:

The tire manufacturer recommends the following:

- Tires should be replaced in pairs when not being replaced as a set of four.
- New tires should be installed on the rear axle.
- Inflation pressures are the same as recommended by Jaguar for the P5 (see owner's manual or door sticker).

For additional information, contact:

Pirelli Consumer Affairs at 1-800-327-2442

ORDERING INFORMATION:

<u>SIZE</u>	<u>TIRE MODEL</u>	<u>PIRELLI CATALOG NO.</u>
205/70R15 95V	P4000 Super Touring	9E604A
215/70R15 97V	P4000 Super Touring	9E602A