

Issue:

This bulletin provides specific recommendations when diagnosing and servicing the hoses of the air suspension on 2004 MY-on XJ range vehicles.

Action:

When carrying out air suspension pipe repairs, follow the workshop procedure outlined in JTIS section 204-05 Vehicle Dynamic Suspension, general procedures, air leaks.

A Caution: When diagnosing leaks in the air suspension, do not use soapy water as a means for detecting the source of an air leak. Water can be harmful to the air suspension system, if it enters the air tubing. Use only Gotec Leak Detection Spray, part number C2C 22398, for this purpose.

If instructed to cut the air pipe, you must use one of the hose cutters outlined below:

- Hose cutter 204-494 available from SPX OTC.
- Hose cutter YA 1000A available from Snap-On.