

**S-TYPE**

DATE 6/99

S100-02

SERVICE

TECHNICAL BULLETIN**Passenger Air Bag Warning Label –
Mandatory Installation**MODEL 2000 MY-ON
S-TYPE

VIN L00001-ON

Issue:

National Highway Traffic Safety Administration (NHTSA) legislation has been enacted requiring the **MANDATORY** installation of a Passenger Airbag Warning Label to all vehicles manufactured on or after February 25th 1997. Jaguar Canada has a voluntary agreement with Transport Canada to extend the action to the Canadian Market.

This legislation therefore applies to all Jaguar S-TYPE vehicles.

The legislation requires that the label should be positioned so that it is clearly visible to the customer at the time of the vehicle being handed over when first sold as a new vehicle.

Action:

A Passenger Airbag Warning Label, printed on one side in English and on the reverse in French, is supplied with each vehicle for North American Markets. The label is supplied complete with an elastic cord to retain it in position, and should be found located on the lid of the passenger's glovebox, as illustrated on the next page.

It is **MANDATORY** that this label should remain attached to the glovebox lid **at the time of delivery of the new vehicle to the customer.** Dealers are requested to hold a small number of spare labels in their Parts stock to cover the possibility of loss or damage to the original factory-supplied label during the delivery cycle, or should a label become detached and lost while a vehicle is on display in a showroom.

Dealers should ensure that personnel responsible for new vehicle preparation are fully aware of the content of this Technical Bulletin, together with all Sales Staff responsible for the delivery of new vehicles to customers, so that compliance with the NHTSA legislation is observed.

NOTE: This check is part of the new car dealer preparation.

THE FOLLOWING ACTION IS MANDATORY IN USA AND CANADA**PASSENGER AIRBAG WARNING LABEL**

Under NHTSA legislation this instruction applies to all Jaguar S-TYPE vehicles.


Check the following during final dealer preparation of a new vehicle for delivery to the customer, particularly where the vehicle has previously been exhibited in a showroom

prior to sale:

- Ensure that the passenger airbag warning label is attached in a prominent position on the front of the glovebox lid, as illustrated below, so that the label will be fully visible to the customer.
- In French-speaking regions of Canada, the label should be reversed, so that the French text faces outwards.
- Should the label be missing or damaged, supply and attach a new label.

POSITIONING AIR BAG WARNING LABEL

It may be necessary to cut a small 'V' notch in the label, Illustration 1, to provide a positive location for the elastic strap.



Parts Information:

DESCRIPTION

Airbag warning label

PART NUMBER

HJA 8923AA