

Motorized Automatic Diagonal Seat Belts - Limited Lifetime Warranty

MODEL 89-92 Sedan, 88-89 XJS

DATE 2/94

3-120

The motorized automatic seat belts (passive restraints) on 1989 through 1992 MY Sedans, and 1988 and 1989 MY XJS vehicles are now covered by a limited lifetime warranty.

A Quick Reference Guide (S 89) which describes system operation and coverage under the limited lifetime warranty has been mailed to all current owners of these vehicles. Owners have been advised to contact their Jaguar dealer if they believe the motorized seat belts do not operate properly.

Refer to Technical Bulletin 76-91 for diagnostic information.

Warranty Statement

Applicability - All USA specification Jaguar vehicles registered in the USA that are equipped with motorized automatic diagonal seatbelt systems.

Jaguar warrants that for the life of the vehicle, repairs required to correct defects in the mechanical and electrical components of the motorized automatic diagonal seatbelt system will be performed without charge. Any component covered by this warranty found to be defective in material or workmanship will be repaired, or replaced, without charge by an authorized Jaguar dealer.

Warranty Coverage

The Motorized Automatic Diagonal Seat Belts Lifetime Limited Warranty covers the following specific components:

- Motorized winch assemblies
- Guide rails
- Electronic control module
- Docking switches (XJS models only)
- Diagonal seatbelt and inertia reel assembly

Only authorized Jaguar dealers may perform repairs, adjustments, and replacement of parts under this limited warranty. If the system has been tampered with so that it does not function as designed, the warranty will be voided.

Items Not Covered

The following items are not covered under the limited warranty:

- Guide rail lubrication (maintenance item)
- Repair or replacement of parts not listed above under "Warranty Coverage"
- Towing (vehicles with remaining New Car Warranty are covered under Royal Charter Care Roadside Assistance)

NOTE: Under certain vehicle operating conditions, the normal locking function of the inertia reel assembly may cause the diagonal belt to momentarily remain secured and prevent occupant exit. THIS CONDITION IS NOT A SYSTEM FAULT - no repairs should be attempted, refer to Quick Reference Guide S 89, or Technical Bulletin 76-91.

Claim Submission Procedures

Claim submission procedures are the same for all vehicles regardless of New Car Warranty status.

Submit claims using standard claim submission procedures. Enter Service Action Code S-427 in place of the normal fault code. The applicable repair operations should be selected from the Jaguar Warranty Codes and Repair Times Manual based on the work performed.