

V8 XJ Series/XK8

DATE 12/98

303-31

SERVICE

TECHNICAL BULLETIN

Replacement Cylinder Heads – Preparation for Normally Aspirated Engines With VVT Feature – Procedure MODEL 1997-98 MY XK8 Range 1998 MY V8 XJ Series VIN 001001-031302

001001-031302 812256-853935

Issue:

Cylinder heads are supplied by Jaguar Parts as a common part for all three versions of the V8 engine: 3.2 Liter (non-NAS), 4.0 Liter normally aspirated and 4.0 Liter supercharged.

The oil supply gallery for the Variable Valve Timing (VVT) unit that is present on all these cylinder heads is plugged which makes the cylinder head **non-VVT** specification as used on supercharged engines.

When a replacement cylinder head is installed on an engine that is equipped with VVT units, the plug must first be removed to permit VVT operation on that cylinder bank. The aluminum blind rivet plug in the VVT supply gallery is secured in position similar to a pop rivet in that the center pin and cone is pulled to expand the rivet until the pin shears below the head. This leaves the aluminum plug and the head of the pin in position to seal the gallery.

Action:

When installing a replacement cylinder head on a normally aspirated 1997-98 MY V8, proceed as follows to remove the blind rivet plug:

- 1. Place the cylinder head on a clean workbench area with access to a compressed air supply.
- 2. Identify the VVT supply gallery and the 8 mm. plug. (bold arrow, Illustration 1).




ILLUSTRATION 1



- 3. Use a 3 mm. (1/8") punch to drive the pin and cone (A, Illustration 1) through the center of the plug until they drop behind the plug.
- 4. Use a screw extractor to remove the plug (B, Illustration 1). The center bore of the plug is 6 mm. (7/32") diameter.
- 5. Use a magnet to probe the gallery to locate and remove the pin and cone.
- 6. Identify the oil supply gallery in the lower cylinder head face and then apply a clean compressed air supply to blow out any debris that may be lying in the VVT supply gallery.

A Warning: Wear safety goggles or other suitable eye protection when blowing out debris.

Parts Information:

<u>DESCRIPTION</u> <u>PAI</u>	RT NUMBER
-------------------------------	-----------

Cylinder head - A bank (right) without valves and springs
Cylinder head - B bank (left) without valves and springs
Cylinder head - A bank (right) with valves and springs
Cylinder head - B bank (left) with valves and springs
Cylinder head - B bank (left) with valves and springs
NCA 2603AF
NCA 2604AB
NCA 2605AB

Note: The cylinder heads listed above can be installed on all versions of the 1997 MY or 1998 MY V8 engine, i.e. 4.0L & 4.0L SC. **This information is not applicable to 1999 MY vehicles.**

Warranty Information:

R.O.		TIME
<u>NUMBER</u>	<u>DESCRIPTION</u>	ALLOWANCE
12.30.12	Conversion of Cylinder head from	0.10 hrs.
	non-VVT to VVT specification	

Page 2 of 2 Bulletin Number 303-31 Date of issue 12/98