



Sedan Range

DATE 2/95

13-07

SERVICE

TECHNICAL BULLETIN

Front Door Seals – Interference with B/C
Post – Modified Seals

MODEL 1995 MY
Sedan Range
VIN
728987-ON

ISSUE:

Modified front door primary seals were introduced at the front doors, from VIN 728987.

The new seals overcome the condition experienced on certain earlier 1995 MY Sedan Range vehicles, where interference occurred between the seals and the B/C posts.

PARTS INFORMATION:

DESCRIPTION

Left front door seal
Right front door seal

PART NUMBER

HNA 5301AD
HNA 5300AD